


| Bill of Material | | | |
|------------------|----------------------|-----------|----------|
| No. | Plan | Article | Quantity |
| 1 | Side Frame Tooth | E00032335 | 1 |
| | Side Frame Gasspring | E00031178 | 1 |
| 2 | Cross | E00023449 | 1 |
| 3 | Footrest B06 | EC00219 | 1 |
| 4A | Armrest Bi5 | E001038 | 2 |
| 4B | Armrest B03 | E000835 | 2 |
| 5 | Brakes | E00023606 | 1 |
| 6 | Upholstery | E00023607 | 1 |

| | | | |
|------------------------|------------|------------|------------|
| V500 Light 30 Exploded | | | |
| Scale: 1:1 | Drafted | Verified | Confirmed |
| Date | 2022-03-03 | 2022-03-03 | 2022-03-03 |
| Initials | PM | AZ | TK |

| |
|---|
| --- |
| Plan No. |
| E00031406/A.1 |
|  |